

SUPERVISION |
COMPLETE ASSEMBLY |
PARTIAL ASSEMBLY |
COMMISSIONING |
REPAIR |
INSPECTION |
FAULT ANALYSIS |
TRAINING



MAINTENANCE & REPAIR

INDUSTRY & SECTOR

Cementplant



Replacement of rails on a Pan Conveyor

ASSIGNMENT

- Replacing the splints in the upper and lower run
- · Checking and correcting the alignment



ORDER FULFILMENT

- Detailed development of an assembly concept
- Close coordination with the customer to ensure line operation of the machine
- Precise resource and time planning

PROJECT CHALLENGES

- Replacement of 450m of rails without dismantling the conveying strand
- · Checking and correcting the alignment without dismantling the conveying strand
- Line operation of the machine had to be ensured during installation
- · Completion including commissioning after 2 weeks

AUMUND GROUP Field Service GmbH

Heydecker Straße 145 46495 Rheinberg / Deutschland Tel.: +49 2843 72 - 458 www.aumund.com



www.aumund.com

https://de.linkedin.com/company/aumund-group